

# **Wind farm owner's view on rotor blades – from O&M to design requirements**

**BREMEN 25-27, February 2013**


**Antonio Herrera Sierra  
Eduardo García Pérez**

# Wind farm owner's view on rotor blades – from O&M to design requirements

---



- Large and heterogeneous fleet of blades
- Typical failures in WTG blades
- Inspections
- How set up a root cause analysis from owner perspective
- Interaction between WTG manufacturer and wind farm owner
- Repairs
- Main challenges and future scenarios

# EDP Renewables






# EDPR-EU fleet

Present fleet of EDPR in **Europe** has **3101 WT** with the following characteristics:



# Blades on EDPR-EU fleet


- **4124 MW** installed capacity (EU, December 2012)
- **3101** wind turbines
- **9303** blades
- Some **33.620 tons** of composite material in total
- Lengths from **15 to 55 m**
- Weights from **750 to 13752 kg**
- Ages from **16 years to some months**
- Materials: glass fiber, carbon fiber, polyester resin, vinyl ester resin, epoxy resin, balsa wood, birch wood



# European fleet maintained directly by EDPR

EDPR in Europe has **3101 WT** :

- **1348 WT managed by EDPR (43%)**
- **1753WT managed by WT OEM (57%)**



# Covering the blade maintenance service

---

## Framework agreement with 4 companies for inspections and repairs

- It is planned an **inspection campaign** for each wind farm 6 months before, adjusted 1 month before and confirmed 1 week before
- All blade **technicians** supply their **CV**
- Repairs are proposed base on inspections results and according to a **procedure** that must be **approved by the owner**
- **Reports** of inspections and repairs according to an **standard** and delivered 1 week after the works
- Teams of 2-3 technicians per wind turbine
- **Prices closed** for each work, calculated according to a unitary prices agreement:

→ *Price of Inspection = f (number of blades ; longitude of blades ; modality of access ; distance to the ISP base)*

→ *Price of Repair = f (number of working hours ; hub height ; modality of access ; distance to the ISP base)*

# Inspections


---

- Visual inspection from the ground through powerful telescopes
  - 100% six months before the end of warranty
  - 33% - 50% each year after warranty
- Visual inspection at height by lifting platforms or rappelling techniques or crane with platform in cases where it is needed a more deep inspection





# Inspections

 <b>renewables</b>  Categorización de daños en palas	Tipo documento:	Informe Técnico
	Código Documento:	
	Fecha:	2011-12-04
	Asunto:	00
		Página: 15 of 18

Para categorizar los daños en el borde de ataque se sugiere la siguiente tabla e imágenes. Los daños en la tabla están referidos a las partes mostradas en la figura 1 de la página 8 del presente documento.

Categoría	Daños en cada parte de la pala
1	Sin daños
2	<10% de pérdida de pintura y agujeros puntuales de poca importancia
3	10-25% de pérdida de pintura y erosión leve del laminado
4	25-40% de pérdida de pintura, erosión moderada del laminado
5	>40% de pérdida de pintura, erosión grave del laminado

Tabla 2. Categorización de daños en el borde de ataque



Figura 16. Daños categoría 2 borde de ataque



Figura 17. Daños categoría 3 borde de ataque



Figura 18. Daños categoría 4 borde de ataque



Figura 19. Daños categoría 5 borde de ataque

Dpto. O&M

Looking for a common basis:

- Development of **failure categorization** criteria
- Development of **decision making strategy** depending on failure category
- Development of **visual guidelines** to be used by site managers and inspection service providers

Category	Repair Priority	Blade Inspection Description/Findings	Continue to Run / Take Offline?	Action
1	None	Blade is in good working condition typical for it's age with possible signs of minor wear	Continue to Run	No action necessary
2	None	Blade shows early signs of wear or damage	Continue to Run	Monitor & Repair within 1 year
3	Low	Blade shows significant signs of wear or damage	Continue to Run	Monitor & Repair within 6 months
4	Medium	Blade shows advanced signs of wear or damage and should be scheduled to be repaired before	Continue to Run	Monitor & Repair within 3 months
5	High	Blade has failed or must be taken out of service to prevent further damage	Take Offline	Repair or Replace Immediately

# Inspections results

---

Example of a wind farm with 67 WT inspected after 14 years of operation:

	Nº of blades (total 201)	% affected blades
Leading Edge Erosion	174	87%
Severe leading edge erosion	100	50%
Dirtiness, grease	197	98%
Gel coat debonding	54	27%
Transversal crack in pressure side	45	22%
Broken trailing edge	3	1%
Leading edge debonding	9	4%
Covered drain holes	6	3%

Typical defects due to aging and working hours



# Inspections results

Example of a wind farm with 7 WT inspected after 5 years of operation:

WTG	BLADE	Damages to the coat					Damages to lamination							Damages to aerodynamic parts		Damages in LPS receptor		Dirt	
		Erosion of LE	Pitting on LE	Peeling of coat	Pitting	Crack in coat	Crack in bonded joint of LE	Crack in lamination or PVC of LE	Crack in TE	Fracture of fabrics of TE	Crack in bonded joint of TE	Damages to shell lamination	Crack in lamination of shell	Broken or damaged VG's	Absence of Stall List Broken Stall List	Fusion of LPS screw	Absence of LPS screw	Presence of oil/grease	Dirt
1	1																	X	
	2								POS			X		X		X		X	
	3										POS					X		X	
2	1																		
	2												X						
	3														X				
3	1													X					
	2									X	X								
	3		X											X					
4	1								X							X		X	
	2																	X	
	3															X		X	
5	1																	X	
	2														X			X	
	3															X		X	
6	1				X														
	2																	X	
	3														X				
7	1				X											X			
	2																		
	3															X			
Total		0	1	0	2	0	0	0	1	1	1	1	1	3	3	7	0	10	0
% Damages		0%	5%	0%	10%	0%	0%	0%	5%	5%	5%	5%	5%	14%	14%	33%	0%	48%	0%

The aging is not an issue in a wind farm with 5 years

# Repairs



CIMG1014



CIMG1017



CIMG1018



CIMG1019




CIMG1020



CIMG1026

# Up-Tower Repairs



Example of a blade tip damaged by lightning.  
Repaired Up-Tower



- It is used a crane with platform. Some companies have developed self-propelled platform lifts.
- Repairs that can be done:
  - Surface cleaning.
  - Leading edge wear.
  - Leading edge and trailing edge cracks and debondings.
  - Detachments of the external coats.
  - In some cases: important structural root cracks.
- Repairs are done by the blade manufacturer (usually if blades are under warranty) or by a ISP.



# Down-Tower Repairs



# Repairs

## LAMINATE SCHEDULE

1 (Top Layer)


2

3


4

5

6





Type of Material	Zstart	Zfinish	Length	Width
Biax 600 H.P	18150	18550	400	200
Biax 600 L.P	18150	18550	400	200
Triax 900 H.P	18075	18625	550	250
Triax 900 L.P	18075	18625	550	250
Biax 600 grapa	17975	18725	750	350
Biax 600 grapa	18025	18675	650	300



Vacuum and  
post-cured



# Repairs

## LAMINATE SCHEDULE





# Repairs



$F$	Total force [N] from a portion of the original blade that is going to be transferred to a portion of the new fabric.
$L_L$	Length [mm] of the portion in longitudinal direction, covered with adhesive, and where the original blade and the new fabric are overlapped.
$L_T$	Length [mm] of the portion in transversal direction, covered with adhesive, and where the original blade and the new fabric are overlapped.
$f$	Load per unit length [N/mm] (transversal direction) in the blade portion of in the new fabric.
$\tau$	Shear stress [N/mm <sup>2</sup> ] in the adhesive.


$$f = \frac{F}{L_T} \quad \therefore \quad \tau = \frac{F}{L_L \cdot L_T} = \frac{f}{L_L}$$

# Major Correctives of blades



Average Annual Failure Rate below 1% (0.5 – 0.75%)  
Some years there is a peak because of a massive blade failure (design or manufacturing error) or a particularly aggressive lightning storm season

Some damages on blades require disassembly the blade to repair on the ground, or in a workshop or even require to replace the blade by another one



# Key points to manage Technical Issues in EDPR fleet

## Technical Knowledge

### Mechanical Engineers group

- Structural and Aerodynamic experience
- Composite structure manufacture skills
- Composite design

## Blade Failure Data Base

### EDPR data base with information of 7000 assets

- Breakdown by technology and wind farm
- Traceability from failure until applied solution

## Work Methodology

### Establish internal rules

- Feedback O&M site managers
- Inspection
- Operation information


## WTG Manufacture & Owner Collaboration

### Relationship & Close Collaboration

- Scheduled Technical Meetings



# Root Cause of Blades Failures




# Topology failure (I)

**Design**

**Understrength laminates**

**Wrong geometry**

**Wrong subcomponent fatigue life**





**Manufacturing Process**

**De-bonding**

**Delamination**

**Wrinkles**

**Resin Voids**




# Topology failure (II)

**Lightning**

**Insurance Damage**

**Bad behavior of the system**



**Erosion**

**Leading edge**

**Gel Coat**



# Information Management

5272 WTGs which implied  
15816 blades



Data Base with the traceability and  
solution of each failure occurred in the fleet

IMAS NEO - 04. Por Tipología - IBM Lotus Notes

File Edit View Create Actions Tools Window Help

Open Home Antonio Herrera Sierra - Correo IMAS NEO - 04. Por Tipología

Search IMAS NEO - 04 Untagged

**Breakdown by Technology, User, Installation & Topology**

Estás aquí: Menú Principal \ Vistas Usuario \ Por Tipología

Salir Informa

Crear Incidencia Crear Incidencia Genérica Mover a Mis Incidencias Búsqueda Ayuda

**Menú Principal**

- Crear
  - Nueva Incidencia
  - Nueva Inc. Genérica
  - Nueva Solicitud
- Vistas
  - General
  - Por Estado
  - Por Usuario
  - Por Instalación
  - Por Tipología
  - Por Fabricante
  - Mis Incidencias
  - Ayuda

**Search in View '04. Por Tipología'**

Indexed ? x

Search for Search Search tips More

- Baseframe
- Electric System
- Foundations
- Gear box
- General
- Hidraulic System
- High-speed shaft & Generator
- Noise
- Orientation System
- Power Curve
- Remote control/Telecontrol System
- Rotor & Low-speed shaft

Imprimir Acciones Genéricas Ciclo Incidencia

**Cases by wind farms components**



# Information Management

Rotor & Low-speed shaft		
HYG-HYG/12/00001		SL Grietas en Palas LM37.3
KOR-KOR/12/00001		SL Failure on blade beam
	14/12/2012 09:42:33	Evaluación - Antonio Herrera Sierra
	13/12/2012 14:13:05	Identificación Coordinador - José Ángel Díaz Álvarez
	13/12/2012 12:43:05	Informe - Antonio Herrera Sierra - Información Gamesa
	10/10/2012 10:45:08	Apertura incidencia - Antonio Herrera Sierra

## Assessment:

- Technical assessment
- First approach of solution

## Open Incidence:

- Brief Description
- Attached information and pictures

* País:	España	Departamento:	
* Tipo de Instalación:	Wind Power Plant	* Instalación:	P.E. Korse / P.E. Korse
* Sistema:	Wind Turbine Generator (WTG)	* Tipología:	Rotor & Low-speed shaft
* Fabricante:	Gamesa	* Modelo:	G-90

**Descripción**

\* Título: Failure on blade beam

\* Descripción: Failure has been produced in one blade of AG-3 in Korszse. This failure has occurred in other EDRP wind farms

\* Criticidad: ☒ Alta ☐ Media ☐ Baja

**Alcance de la Incidencia:**  
This failure is a fabrication problem which can affect to the rest of the wind farm.

Field Report WF Korszse AG-3.pdf IMG\_0909.jpg IMG\_0913.jpg IMG\_0916.jpg IMG\_0919.jpg IMG\_0921.jpg IMG\_0930.jpg IMG\_0934.jpg IMG\_0944.jpg IMG\_0946.jpg

Antonio Herrera Sierra Fecha: 14/12/2012 09:42:33

\* Evaluación:

GSX blades have developed different failures topology (broken beam, mid radius cracks, peel-off shells and lightning). The scope is analyzed the failure produced and ask technical information Gamesa in order to detect what's root cause analysis. This incidence can relate to Guadataba incidences due to is the EDRP-EU wind farm where major blades failures have been developed.

**Posibles Repercusiones Futuras:**  
Out guarantee risks





# Work Methodology (I)

---

**O&M  
Notification**

**Engineering  
Group**

## First Approach

---


- Call Conference site and regional manager
- First failure pictures
- Go to site and survey the failure zone



# Work Methodology (II)


## Information Analysis

- Post-process site information
- Download operation information (log book, Scada data etc.)
- Cross information with other stored cases and WTG manufacturer






## Solution Proposal

- Incident report
- Follow-up recommendations



# Design Failure – Root cracks




$$D = 6.919 \times 10^{-3} \frac{N_{max}}{((\sigma_s / \bar{\sigma}) - 2.67)^9}$$

This stress is influenced by concentrated factor, which was higher due to manufacturer process


# Design Failure – Root cracks and web delamination




Bad blade design induced that 1 year after operation started some blades collapse.



All fleet was repaired, EDPR was close of WTG manufacturer to define the correct reparation.



# Design Failure – Edgewise vibration (I)



Blades with dampers which permit damping the edgewise vibration.





Visual inspections and increase of shutdowns permit detect the problem.



# Design Failure – Edgewise vibration (II)

Vibration levels are lower with higher wind speed



Sum of Number of Records (copy 2) and Number of Records (DOTS) for each WTG. For pane Sum of Number of Records (copy 2): Color shows details about Color Legend. The marks are labeled by sum of Number of Records (copy 2). For pane Number of Records (DOTS): The marks are labeled by Finish of Implementation. The context is filtered on EventText, TimeFrom and windfarmid. The EventText filter keeps 393 Vibration TAC84. The TimeFrom filter ranges from 1/1/2011 12:00:00 AM to 11/21/2012 09:08:00 PM. The windfarmid filter keeps BECHTE.

Level Vibration Decrement continue from dampers were repaired in the two alarm frequencies


- 1.17 Hz – 0.45 m/s<sup>2</sup> First Center Frequency
- 1.66 Hz – 0.45 m/s<sup>2</sup> Second Center Frequency

Retrofit applied has solved the losses due to WTGs shutdowns

# Manufacturing process – Wrinkles

Compression stress in suction shell

Tension stress in the pressure shell



Wrinkles induced that in the compressed laminated appears micro-buckling which induced a crack that grow up in all thickness.

RCA

- Error during lay-up.
- Error during curing process.



# Lightning

- o The IEC 61400-24 establishes the annual frequency of lightning flashes attaching a wind turbine calculated as:

$$\text{Efficiency} = 1 - N_{\text{cna}} / N_{\text{dtotal}} > 0,98 \text{ for a LPL I according to IEC 61400-24:2010}$$

, being:

$$N_{\text{dTotal}} = N_{\text{d}} \cdot N_{\text{WT}}$$

$$N_{\text{D}} = N_{\text{g}} \cdot A_{\text{d}} \cdot C_{\text{d}} \cdot 10^{-6}$$

$N_{\text{dTotal}}$ : Number of annual expected lightning flashes in WF  
 $N_{\text{WT}}$ : Number of wind turbines in the WF  
 $N_{\text{D}}$ : Number of annual expected lightning flashes  
 $N_{\text{g}}$ : Number of lightning flashes per year and square Km  
 $A_{\text{d}}$ : Collection area of the structure  
 $C_{\text{d}}$ : Environmental factor

Cable receptor



Lightning was not absorbed by tip receptor.

- Necessity to improved tip zone
- Introduce upgraded as Diverter Strips



# Erosion

The tip of a blade travels in 1 week a distance equivalent to a round to the world.





Blade tip linear speed = 250 km/h

24 h / 7 d  $\rightarrow$  42 000 km


Earth perimeter = 40 077 km



- Lack of protection against UV and water.
- De-rated power curve.



# Summary of blades damages



## CAUSES:

- Wrinkles
- Undulations
- Waviness
- Bonding defects
- Resin voids
- Dry areas
- Delaminations
- Ply drops
- Buckling
- Lightning
- Friction wear

# Main challenges and future scenarios

---

- Most of blade failures and deteriorations can be repaired and there is a market of ISP with enough capacity to do it. But in a few occasions (example lightning) damages are so important that it is not possible to repair and it is needed to replace.... Are there blade stored anywhere? **Is any company interested in sharing stocks of blades?**
- Material degradations with temperature, humidity, UV radiation? **Is it a certain risk the physicochemical degradation of the composites in 20-25 years?**
- In industry in general there is an important tradition manufacturing and repairing electrical and mechanical devices, so the service market created for wind industry has the benefit of this knowledge. But it is not the case of blades, where there is not a tradition. So we are repairing with 1-2 years warranty period, but maybe a potential failure will require 3-5 years to develop. **Certified repairs and companies?**
- Introduce new advanced NDT techniques to control manufacture problems. Increase Q&A measures

**It is needed to change the present short term business relationship of selling/purchasing between WT manufacturer/owner to a long term collaborative relationship between the blade manufacturer/owner.**

# Question?

---

